MARION COUNTY SURVEYOR'S OFFICE

SECTION CORNER RECORD

SEC. 35 TWN. 15_{N} RNG. 3_{E}

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR

Date: 7-30-09

Party Chief: Wilcoxen

Crew: Finney

Type of Marker: 5/8" rebar set in W-bank of ditch Method of Establishment: County: 1-13-2000

IN S.P.C. E Zone, NAD 83

DEBRA S. JENKINS

MARION COUNTY SURVEYOR

Name: 15033507 N: 493 532.604 0(m)

56 207.145 0(m) Line of Thompson Rd 5000 S ж Т 21.00 89.45 60.72

74.67 4. Section Line 5000 S 65.55

69.18

Original post set 1820 by Laughlin with witnesses: 20" elm S 70 W 12 links, 6" hornbeam N 70 E 8 links per Marion County Atlas pg. 6. Hosbrook, no date, called corner previously set per Perry Township Legal Survey Book pg. 15. 3-30-1961 MCSO tie card calls for a stone. Excavated 6-25-87 stone found at surface and Harrison Monument set. Retied 10-14-1996 by Wilcoxen. Retied 1-13-2000 by Wilcoxen. Corner reset 4-10-03 with 5/8" rebar as per ties by Wilcoxen. Retied 7-30-09 by Wilcoxen.

REF.	DISTANCE	DESCRIPTION
1.	21.00'	Due E to west face of steel fence post
2.	69.78'	PK nail w/shiner S 15" hackberry 50" up
3.	65.55'	PK nail w/shiner N twin hackberry 50" up
4.	74.67'	Due W to NW corner of 2-14-3 (rebar) (113 links per Wm. B. Laughlin 1820)
5.	89.45'	PK nail S PwP # 85-693 A 28" up
6.	60.72'	PK nail S PwP #86-693 A 50" up
7.	10.30'	Westernmost bolt in headwall